

ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರ ಕಛೇರಿ  
ಲೋಇ, ಬೆಂಗಳೂರು ವಿಭಾಗ,  
ಲೋಇ ಆಫೀಸ್ ಕಟ್ಟಡ 2ನೇ ಮಹಡಿ  
ಕೆ.ಆರ್.ವೃತ್ತ ಬೆಂಗಳೂರು 01



ಕರ್ನಾಟಕ ಸರ್ಕಾರ  
(ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ)

ದೂರವಾಣಿ : 080-22133370  
ಫ್ಯಾಕ್ಸ್ : 080-22133365  
ಇ ಮೇಲ್: eepwdbngdn@yahoo.com

ಸಂಖ್ಯೆ:ಕಾನಿಇಂ:ಬೆಂವಿ:ಎಇ-3:2021-22

A221

ದಿ: 06/12/2021  
"ನೋಂದಾಯಿತ ಅಂಚೆ ಮತ್ತು ಸ್ವೀಕೃತಿ"

ರವರಿಗೆ:-

ಕಾರ್ಯದರ್ಶಿಗಳು,

National Institute of Value Education,  
# 48/10, 13 ನೇ ಅಡ್ಡ ರಸ್ತೆ, 8ನೇ ಮುಖ್ಯ ರಸ್ತೆ,  
ಮಲ್ಲೇಶ್ವರಂ, ಬೆಂಗಳೂರು.

ಮಾನ್ಯರೇ,

ವಿಷಯ:- National Institute of Value Education, # 48/10, 13 ನೇ ಅಡ್ಡ ರಸ್ತೆ, 8ನೇ ಮುಖ್ಯ ರಸ್ತೆ, ಮಲ್ಲೇಶ್ವರಂ, ಬೆಂಗಳೂರು ರವರು ಸರ್ವೆ ನಂ. 19, ಲಕ್ಷ್ಮೀಪುರ ಕ್ರಾಸ್, ಎಂ.ಎಸ್ ಪಾಳ್ಯ ರಸ್ತೆ, ಬೆಂಗಳೂರು-560097 ಇಲ್ಲಿ ತಾವು ನಡೆಸಲು ಉದ್ದೇಶಿಸಿರುವ "BASIL WOODS NATURE SCHOOL" ಕಟ್ಟಡದ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರ ನೀಡುವ ಬಗ್ಗೆ.

ಉಲ್ಲೇಖ:-

1. ದಿನಾಂಕ: 19.09.2020 ರಂದು ಸರ್ಕಾರದ ಪ್ರಧಾನ ಕಾರ್ಯದರ್ಶಿಗಳು, ಪ್ರಾಥಮಿಕ ಮತ್ತು ಪ್ರೌಢ ಶಿಕ್ಷಣ ಇಲಾಖೆ, ಬೆಂಗಳೂರು ರವರ ಅಧ್ಯಕ್ಷತೆಯಲ್ಲಿ ನಡೆದ ಸಭೆಯ ನಡವಳಿ.
2. ಸರ್ಕಾರದ ಸುತ್ತೋಲೆ ಸಂಖ್ಯೆ: ಲೋಇ 59 ಬಿಇಡಿ 2019, ದಿನಾಂಕ: 10.11.2021
3. ಸರ್ಕಾರದ ತಿದ್ದುಪಡಿ ಆದೇಶ ಸಂಖ್ಯೆ: ಲೋಇ 59 ಬಿಇಡಿ 2019, ದಿನಾಂಕ: 20.11.2021.
4. ತಮ್ಮ ಮನವಿ ದಿನಾಂಕ:- 23.11.2021
5. ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು, ನಂ.2 ಉತ್ತರ ಉಪವಿಭಾಗ, ಬೆಂಗಳೂರು ರವರ ಪತ್ರ ಸಂಖ್ಯೆ: 2021-22/554 ದಿನಾಂಕ: 25.11.2021

\*\*\*\*

ಮೇಲಿನ ವಿಷಯಕ್ಕೆ ಸಂಬಂಧಿಸಿದಂತೆ, National Institute of Value Education, # 48/10, 13 ನೇ ಅಡ್ಡ ರಸ್ತೆ, 8ನೇ ಮುಖ್ಯ ರಸ್ತೆ, ಮಲ್ಲೇಶ್ವರಂ, ಬೆಂಗಳೂರು ರವರು ಸರ್ವೆ ನಂ. 19, ಲಕ್ಷ್ಮೀಪುರ ಕ್ರಾಸ್, ಎಂ.ಎಸ್ ಪಾಳ್ಯ ರಸ್ತೆ, ಬೆಂಗಳೂರು-560097 ಇಲ್ಲಿ ತಾವು ನಡೆಸಲು ಉದ್ದೇಶಿಸಿರುವ "BASIL WOODS NATURE SCHOOL" ಕಟ್ಟಡದ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರ ನೀಡಲು ಉಲ್ಲೇಖ (4) ರ ಪತ್ರದಲ್ಲಿ ಕೋರಿರುತ್ತೀರಿ.

ರಿಟ್ ಪಿಟೀಷನ್ (ಸಿವಿಲ್) ಸಂ: 484 (2004) ಗೆ ಸಂಬಂಧಿಸಿದಂತೆ ಸುಪ್ರೀಂ ಕೋರ್ಟ್ ನೀಡಲಾದ ಜಡ್ಜ್‌ಮೆಂಟ್‌ನಲ್ಲಿ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು, ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ ರವರು ಶಾಲಾ/ಕಾಲೇಜು ಕಟ್ಟಡಗಳನ್ನು ಪರಿಶೀಲಿಸಿ "Structurally Stable Certificate" ಅನ್ನು ನೀಡಲು ಆದೇಶಿಸಿರುವುದರಿಂದ ಹಾಗೂ ಉಲ್ಲೇಖ (1) ರ ಸಭಾ ನಡವಳಿಯ ನಿರ್ದೇಶನದಂತೆ ಈಗಾಗಲೇ ನಿರ್ಮಾಣಗೊಂಡು ಅಸ್ತಿತ್ವದಲ್ಲಿರುವಂತಹ ಕಟ್ಟಡಗಳಿಗೆ ರಚನಾತ್ಮಕ (Structural Evaluation) ಮೌಲ್ಯಮಾಪನ ಮಾಡಿಸಿ National Building code ಮಾನದಂಡಗಳ ಅನ್ವಯ ಪ್ರಮಾಣ ಪತ್ರ ನೀಡಲು ಸೂಚಿಸಿರುವುದರಿಂದ ಪ್ರಸ್ತಾಪಿತ ಕಟ್ಟಡದ ಸ್ವಕರಲ್ ಪರೀಕ್ಷೆಗಳನ್ನು ನಡೆಸಿ ಈ ಕೆಳಕಂಡಂತೆ ವರದಿ ನೀಡಲಾಗಿದೆ.

ಬೆಂಗಳೂರು ಉತ್ತರ ತಾಲ್ಲೂಕು, BASIL WOODS NATURE SCHOOL ಸರ್ವೆ ನಂ. 19, ಲಕ್ಷ್ಮೀಪುರ ಕ್ರಾಸ್, ಎಂ.ಎಸ್ ಪಾಳ್ಯ ರಸ್ತೆ, ಬೆಂಗಳೂರು-560097 ಕಟ್ಟಡವನ್ನು ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು, ಲೋಇ, ನಂ.2 ಉತ್ತರ ಉಪ-ವಿಭಾಗ, ಬೆಂಗಳೂರು, Dr. DJ. Suresh Kumar (Tejaswi Construction Company) Registration No-SJN-F139/2011-12 ಹಾಗೂ BASIL WOODS NATURE SCHOOL ಬೆಂಗಳೂರು ರವರ ನೋಂದಾಯಿತ ಸ್ವಕರಲ್

ತಳಮಹಡಿಯಲ್ಲಿ ಉಗ್ರಾಣ, ಶೌಚಾಲಯ, 4 ಸಂಖ್ಯೆ ಪ್ರಯೋಗಾಲಯ ಕೊಠಡಿಗಳು, ಮೆಟ್ಟಿಲುಕೋಣೆ ಇರುತ್ತದೆ. ನೆಲಮಹಡಿಯಲ್ಲಿ ಕಂಪ್ಯೂಟರ್ ಲ್ಯಾಬ್, ಉಪನ್ಯಾಸ ಕೊಠಡಿಗಳು, ಲೈಬ್ರರಿ, ಆಡಳಿತ ಶಾಖೆ, ಮೆಟ್ಟಿಲುಕೋಣೆ ಹಾಗೂ ಶೌಚಾಲಯಗಳು ಇರುತ್ತವೆ. ಮೊದಲನೇ ಮಹಡಿಯಲ್ಲಿ ಉಪನ್ಯಾಸ ಕೊಠಡಿಗಳು, ಲೈಬ್ರರಿ, ಆಡಿಟೋರಿಯಂ, ಮೆಟ್ಟಿಲುಕೋಣೆ ಹಾಗೂ ಶೌಚಾಲಯಗಳು ಇರುತ್ತವೆ. ಮೆಟ್ಟಿಲುಗಳನ್ನು NBC Code-2016 ರನ್ವಯ ನಿರ್ಮಿಸಲಾಗಿರುತ್ತದೆ. ಸದರಿ ಕಟ್ಟಡದಲ್ಲಿ ಶೌಚಾಲಯ ಮತ್ತು ಕುಡಿಯುವ ನೀರಿನ ವ್ಯವಸ್ಥೆ ಕಲ್ಪಿಸಲಾಗಿರುತ್ತದೆ.

ಮುಂದುವರೆದು, ಕಟ್ಟಡದ ಸುರಕ್ಷತೆಗೆ ಸಂಬಂಧಿಸಿದಂತೆ, ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು, ನಂ.2 ಉತ್ತರ ಉಪವಿಭಾಗ, ಬೆಂಗಳೂರು ರವರು ಉಲ್ಲೇಖ (5) ರ ಪತ್ರದಲ್ಲಿ ಕಟ್ಟಡದ ಕಾಂಕ್ರೀಟ್ ಸದೃಢತೆಯ ಬಗ್ಗೆ ದಿನಾಂಕ:- 29.09.2021 ರಂದು ಕರ್ನಾಟಕ ಟೆಸ್ಟ್ ಹೌಸ್ ಪ್ರೈವೇಟ್ ಲಿಮಿಟೆಡ್-NABL Accredited Laboratory as per ISO/IEC 17025 ರವರು PUNDIT 6 Portable ultrasonic non-destructive Digital indicating Tester ಮುಖಾಂತರ Ultrasonic Pulse Velocity Test ಮುಖಾಂತರ ಪರೀಕ್ಷೆಗಳನ್ನು ಕೈಗೊಂಡು, ಸಮಾಲೋಚಕರೊಂದಿಗೆ ಉಪವಿಭಾಗದ ತಾಂತ್ರಿಕ ವರ್ಗವು ನಡೆಸಿರುವ ಪರೀಕ್ಷಾ ವರದಿಯಂತೆ ಕಟ್ಟಡವು ಸದೃಢತೆಯಿಂದ ಇರುವುದು ಕಂಡುಬಂದಿರುತ್ತದೆಂದು ವರದಿ ಮಾಡಿರುತ್ತಾರೆ. ಉಲ್ಲೇಖ (2) ಮತ್ತು (3) ರ ಸರ್ಕಾರದ ಪತ್ರಗಳಲ್ಲಿ ಸೂಚಿಸಿರುವಂತೆ ಮೌಲ್ಯಮಾಪನ ಶುಲ್ಕವಾದ ಕಟ್ಟಡದ ಮೌಲ್ಯದ ಶೇ. 0.05% ರಷ್ಟು ಮೊತ್ತ ರೂ. 34,500/- (ರೂ. ಮೂವತ್ತಾ ನಾಲ್ಕು ಸಾವಿರದ ಐವತ್ತು ರೂಪಾಯಿಗಳು ಮಾತ್ರ) ಗಳನ್ನು BASIL WOODS NATURE SCHOOL ರವರು EQUITAS ಬ್ಯಾಂಕ್, ಬಸವೇಶ್ವರನಗರ ಡಿ.ಡಿ. ಸಂಖ್ಯೆ 002286 ದಿನಾಂಕ : 29.11.2021 ರಲ್ಲಿ ಪಾವತಿಸಿರುತ್ತಾರೆ.

- BASIL WOODS NATURE SCHOOL ಕಟ್ಟಡವನ್ನು National Institute of Value Education" ರವರ ಮನವಿ ಪತ್ರದಲ್ಲಿ ಸರ್ವೆ ನಂ. 19, ಲಕ್ಷ್ಮೀಪುರ ಕ್ರಾಸ್, ಎಂ.ಎಸ್. ಪಾಳ್ಯ ರಸ್ತೆ, ಬೆಂಗಳೂರು ಇಲ್ಲಿ ನಿರ್ಮಿಸಲಾಗಿರುವುದಾಗಿ ತಿಳಿಸಿರುತ್ತಾರೆ. ಅದರಂತೆ ಕಟ್ಟಡವನ್ನು ಸದರಿ ಸ್ಥಳದಲ್ಲಿ ನಿರ್ಮಿಸಲಾಗಿರುತ್ತದೆ.
- ಕಸಫಟ್ಟಪುರ ಗ್ರಾಮ ಪಂಚಾಯಿತಿ, ಹೆಸರಫಟ್ಟ ಹೋಬಳಿ, ಯಲಹಂಕ ತಾಲ್ಲೂಕು, ಬೆಂಗಳೂರು ರವರಿಂದ ಅನುಮೋದನೆಯಾದ ನಕ್ಷೆಯಂತೆ BASIL WOODS NATURE SCHOOL ಕಟ್ಟಡವನ್ನು ನಿರ್ಮಿಸಲಾಗಿರುತ್ತದೆ.
- ಸದರಿ ಕಟ್ಟಡವನ್ನು Dr. DJ. Suresh Kumar (Tejaswi Construction Company) Registration No-SJN-F139/2011-12 ಸಂಸ್ಥೆ ರವರು ನೀಡಿರುವ ಸ್ಪಷ್ಟರಲ್ ವಿನ್ಯಾಸದಂತೆ ನಿರ್ಮಿಸಲಾಗಿರುತ್ತದೆ.

Ultrasonic Pulse Velocity Test

Conducting Ultrasonic pulse velocity test for compressive strength of in-situ concrete on Columns, Beams and Slab at Critical points using "PUNDIT 6" (Portable ultrasonic non-destructive Digital indicating Tester) equipment form M/s. CNS FARNELL U.K, as per the guidelines in Indian Standards (IS: 516 (Par 5/Sec 1):2018) ಪರೀಕ್ಷೆಯನ್ನು M/s Karnataka Test House Pvt. Ltd ರವರು ಕೈಗೊಂಡಿದ್ದು, ಸದರಿ ಪರೀಕ್ಷೆಯಲ್ಲಿ ಕಟ್ಟಡವು ಉತ್ತಮ ಗುಣಮಟ್ಟದಿಂದ ಕೂಡಿರುವುದು ಕಂಡುಬಂದಿರುವುದಾಗಿ ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು, ನಂ.2 ಉತ್ತರ ಉಪವಿಭಾಗ, ಬೆಂಗಳೂರು ರವರು ವರದಿಸಿರುತ್ತಾರೆ.

- Recognizance, visual inspection of Building-cracks, distress, dampness etc. ಪರೀಕ್ಷೆಯನ್ನು M/s Karnataka Test House Pvt. Ltd ರವರ ಜೊತೆ ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆಯ ತಾಂತ್ರಿಕ ತಂಡದೊಂದಿಗೆ ಕೈಗೊಳ್ಳಲಾಗಿರುತ್ತದೆ. ಸದರಿ ಪರೀಕ್ಷೆಯಲ್ಲಿ ಕಟ್ಟಡವು ಉತ್ತಮ ಗುಣಮಟ್ಟದಿಂದ ಕೂಡಿರುವುದು ಕಂಡುಬಂದಿರುವುದಾಗಿ ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು, ನಂ.2 ಉತ್ತರ ಉಪವಿಭಾಗ, ಬೆಂಗಳೂರು ರವರು ವರದಿಸಿರುತ್ತಾರೆ.

ಕಟ್ಟಡವು ಸುರಕ್ಷಿತವಾಗಿರುವುದಾಗಿ National Building code of India ಮಾನದಂಡದಂತೆ ನಿರ್ಮಿಸಿ ಸುರಕ್ಷಿತವಾಗಿರುವುದಾಗಿ Dr. DJ. Suresh Kumar (Tejaswi Construction Company) Registration No-SJN-F139/2011-12 ರವರು ಧೃಢೀಕರಿಸಿ ನೀಡಿರುವ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ಸಂಸ್ಥೆಯವರು ಒದಗಿಸಿರುತ್ತಾರೆ.

National Building code of India 2016 ರ ಅನ್ವಯ Certificate for Structural Design Sufficiency ಪ್ರಮಾಣ ಪತ್ರವನ್ನು Dr. DJ. Suresh Kumar (Tejaswi Construction Company) Registration No-SJN-F139/2011-12 ರವರು ನೀಡಿರುತ್ತಾರೆ. (Annex-C)

BASIL WOODS NATURE SCHOOL  
PRINCIPAL  
DISE CODE : 29284100969  
Sy. No. 19, Guniagrahara Village,  
Lakshimpura Cross, Hesaraghatta Hobli,  
Bangalore North - 560097.

EXECUTIVE DIRECTOR  
TOOCHS ERECTION SDOOM TISSE  
69600148262 : SDOO ASD  
Sy. No. 19, Guniagrahara Village,  
Lakshimpura Cross, Hesaraghatta Hobli,  
Bangalore North - 560097.

Alek



- National Building code of India 2016 ರ ಅನ್ವಯ Engagement of Builder / Constructor ಪ್ರಮಾಣ ಪತ್ರವನ್ನು  
Dr. DJ. Suresh Kumar (Tejaswi Construction Company) Registration No-SJN-F139/2011-12  
ರವರು ನೀಡಿರುತ್ತಾರೆ. (Annex-D)

ಸದರಿ ಸಂಸ್ಥೆಯವರು ನೀಡಿರುವ ಎಲ್ಲಾ ದಾಖಲೆಗಳನ್ನು ಪರಿಶೀಲಿಸಲಾಗಿ M/s Karnataka Test House Pvt. Ltd & Dr. DJ. Suresh Kumar (Tejaswi Construction Company) Registration No-SJN-F139/2011-12 ರವರು ಕಟ್ಟಡವು ರಚನಾತ್ಮಕವಾಗಿ ಸುರಕ್ಷಿತವಾಗಿದೆಯೆಂದು ನೀಡಿರುವ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ಪರಿಗಣಿಸಿ ಹಾಗೂ ಕಟ್ಟಡವನ್ನು ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆಯ ತಾಂತ್ರಿಕ ತಂಡ ನೀಡಿರುವ ವರದಿ ಹಾಗೂ ಮುದ್ದು ಪರಿಶೀಲಿಸಿ ಕಟ್ಟಡವು Structurally Stable ಇರುವುದಾಗಿ ಪರೀಕ್ಷಾವರದಿಗಳಿಂದ ಕಂಡುಬಂದಿರುವುದರಿಂದ, ಈ ಕೆಳಗೆ ಸಹಿ ಮಾಡಿರುವವರು ದಿ: 04.12.2021 ರಂದು ಮುದ್ದಾಗಿ ಪರಿವೀಕ್ಷಿಸಿದ್ದು BASIL WOODS NATURE SCHOOL ಕಟ್ಟಡವು Structurally Stable ಇದೆ ಎಂದು ನಿರಾಕ್ಷೇಪಣಾ ಪತ್ರವನ್ನು ಈ ಕೆಳಕಂಡ ಷರತ್ತುಗಳಿಗೊಳಪಟ್ಟು ನೀಡಲಾಗಿದೆ.


- ತಳಮಹಡಿಯ ಶೌಚಾಲಯಗಳು, ನೆಲಮಹಡಿಯ ಕಂಪ್ಯೂರ್ ಲ್ಯಾಬ್, ಸ್ಟಾಫ್ ರೂಂ ಮತ್ತು ಮೊದಲನೇ ಮಹಡಿಯ ಬೋಧನಾ ಕೊಠಡಿಗಳ ಗೋಡೆಗಳಲ್ಲಿ ತೇವಾಂಶವು ಕಂಡು ಬಂದಿದ್ದು, ಕೂಡಲೇ ಸರಿಪಡಿಸುವುದು.
- ಕಟ್ಟಡದ ಸುತ್ತಲೂ ಫ್ಲಾಗಿಂಗ್ ಕಾಂಕ್ರೀಟ್ ಅಳವಡಿಸುವುದು.
- ಹಾಳಾಗಿರುವ ಡಿಸ್‌ಫೋಸಲ್ ಪೈಪುಗಳನ್ನು ಕೂಡಲೇ ಸರಿಪಡಿಸುವುದು.
- ಕಟ್ಟಡದ ತಾರಸಿಯ ಸುತ್ತಲೂ ಅಗತ್ಯ ಎತ್ತರದ ಪ್ಯಾರಾಪೆಟ್ ನಿರ್ಮಿಸುವುದು.

ಉಳಿದಂತೆ, ಪ್ರಸ್ತಾಪಿತ ಕಟ್ಟಡದ Non - Structural Elements (Infrastructural facilities) ಗೆ ಸಂಬಂಧಿಸಿದಂತೆ, ಸಿವಿಲ್ ಇಂಜಿನಿಯರ್, ಆರೋಗ್ಯಾಧಿಕಾರಿ, ಕಂದಾಯ ಅಧಿಕಾರಿ, ಮನಃಶಾಸ್ತ್ರಜ್ಞ, ಅಗ್ನಿಶಾಮಕ ಅಧಿಕಾರಿ, ಸ್ಥಳೀಯ ಸಂಸ್ಥೆಯ ಅಧಿಕಾರಿಗಳೊಳಗೊಂಡ ಪರೀಕ್ಷಾ ತಂಡದವತಿಯಿಂದ ಪರಿಶೀಲಿಸಿ ನಿರಾಕ್ಷೇಪಣಾ ಪತ್ರವನ್ನು ಪಡೆಯತಕ್ಕದ್ದು ಹಾಗೂ "Fire safety Certificate" ಅನ್ನು ಮುಖ್ಯ ಅಗ್ನಿಶಾಮಕ ಅಧಿಕಾರಿಯಿಂದ ಪಡೆಯತಕ್ಕದ್ದು.

ತಮ್ಮ ವಿಶ್ವಾಸಿ,

ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು,  
ಲೋಕ, ಬೆಂಗಳೂರು ವಿಭಾಗ,  
ಬೆಂಗಳೂರು

  
EXECUTIVE DIRECTOR  
BASIL WOODS NATURE SCHOOL  
DISE CODE : 29284100969  
Sy. No. 19, Guniagrahara Village,  
Lakshmipura Cross, Hesaraghatta Hobli,  
Bangalore North - 560097.

  
PRINCIPAL  
BASIL WOODS NATURE SCHOOL  
DISE CODE : 29284100969  
Sy. No. 19, Guniagrahara Village,  
Lakshmipura Cross, Hesaraghatta Hobli,  
Bangalore North - 560097.



# SIU TRANSLATION CENTRE (Regd.)

(Indian & Foreign Languages)

Regd. No. 17/119/CE/0055/2004 Dt.: 10-2-2004 & BBMP Licence No. SO20119645148990121

# 28-A, 2nd Floor, H.M.S. Complex, Cubbonpet Main Road, Behind Halasuru Gate P.S.

Bangaluru - 560 002. Ph. : 93437 77272, 8050538158, 63602 95797 Office Telefax : 48515948

Email : siustranslation@gmail.com

KANNADA version ENGLISH Translated by ..... Muharak Khan B.A. LL.M. KSEF (Ph.D) ..... Pages : 1 to



## Government of Karnataka (Public Works Department)

### Office of the Executive Engineer

Public Works Department, Bangalore Division,  
PWD Annex Building, 2nd Floor, K.R. Circle, Bangalore - 01.

Phone: 080-22133370 Fax: 080-22133365

Email: [cepwdbngrdn@yahoo.com](mailto:cepwdbngrdn@yahoo.com)

No: KaNiE: BeVi:AE-3:2021-22/4221

Date: 06-12-2021

*Registered Post with Acknowledgment Due"*

To:  
The Secretary,  
National Institute of Value Education,  
#48/10, 13th Cross, 8th Main Road,  
Malleswaram, Bangalore.

Respected Sir/Madam,

### Subject:

Issuance of Safety Certificate for the building "BASIL WOODS NATURE SCHOOL," located at Survey No. 19, Lakshmipur Cross, M.S. Palya Road, Bangalore - 560097, proposed to be operated by the National Institute of Value Education, #48/10, 13th Cross, 8th Main Road, Malleswaram, Bangalore.

### References:

1. Proceedings of the meeting chaired by the Principal Secretary to Government, Primary and Secondary Education Department, Bangalore, dated 19.09.2020.
2. Government Order No: LOE 59 BED 2019, dated 10.11.2021.

*Prin.*

PRINCIPAL  
BASIL WOODS NATURE SCHOOL  
DISE CODE : 29284100969  
Sy. No. 19, Guniagrahara Village,  
Lakshmipura Cross, Hesaraghatta Hobli,  
Bangalore North - 560097.

*Alak*

EXECUTIVE DIRECTOR  
BASIL WOODS NATURE SCHOOL  
DISE CODE : 29284100969  
Sy. No. 19, Guniagrahara Village,  
Lakshmipura Cross, Hesaraghatta Hobli,  
Bangalore North - 560097.

3. Government Corrigendum Order No: LOE 59 BED 2019,  
dated 20.11.2021.

4. Your application dated 23.11.2021.

5. Letter No: 2021-22/554, dated 25.11.2021, from the Assistant  
Executive Engineer, North Sub-division, No. 2, Bangalore.

\*\*\*\*\*

With reference to the subject mentioned above, the National  
Institute of Value Education, #48/10, 13th Cross Road, 8th Main  
Road, Malleswaram, Bangalore, has requested in their letter cited in  
Reference (4) to issue a Safety Certificate for the building "BASIL  
WOODS NATURE SCHOOL," proposed to be operated at Survey  
No. 19, Lakshmipur Cross, M.S. Palya Road, Bangalore – 560097.

In accordance with the judgment delivered by the Supreme  
Court in Writ Petition (Civil) No. 484 (2004), the Executive  
Engineers of the Public Works Department have been mandated to  
inspect school/college buildings and issue a "Structurally Stable  
Certificate." Further, as per the directives in the meeting  
proceedings cited in Reference (1), for buildings already  
constructed and in existence, it has been instructed to conduct a  
Structural Evaluation in compliance with the National Building  
Code standards and issue the certificate accordingly. Hence, the

**PRINCIPAL**  
BASIL WOODS NATURE SCHOOL  
DISE CODE : 29284100969  
Sy. No. 19, Guniagrahara Village,  
Lakshmipura Cross, Hesaraghatta Hobli,  
Bangalore North - 560097.

**EXECUTIVE DIRECTOR**  
BASIL WOODS NATURE SCHOOL  
DISE CODE : 29284100969  
Sy. No. 19, Guniagrahara Village,  
Lakshmipura Cross, Hesaraghatta Hobli,  
Bangalore North - 560097.





structural tests for the proposed building have been conducted, and the report is provided as follows.



The building of BASIL WOODS NATURE SCHOOL, Survey No. 19, Lakshmipur Cross, M.S. Palya Road, Bangalore-560097, located in Bangalore North Taluk, has been constructed as per the structural design provided by the Assistant Executive Engineer, Public Works Department, No. 2 North Sub-Division, Bangalore, Dr. DJ. Suresh Kumar (Tejaswi Construction Company), Registration No. SJN-F139/2011-12.

The basement includes a storage room, toilets, 4 laboratory rooms, and a staircase. The ground floor consists of a computer lab, lecture halls, a library, an administrative section, staircases, and toilets. The first floor houses lecture halls, a library, an auditorium, staircases, and toilets. The staircases are constructed as per the NBC Code-2016 standards. Additionally, provisions for toilets and drinking water facilities have been made in the said building.

Further, regarding the safety of the building, the Assistant Executive Engineer, No. 2 North Sub-Division, Bangalore, in his letter cited in Reference (5), has reported that the concrete strength of the building was tested on 29.09.2021 by Karnataka Test House Private Limited – an NABL Accredited Laboratory as per ISO/IEC

**PRINCIPAL**  
BASIL WOODS NATURE SCHOOL  
DISE CODE : 29284100969  
Sy. No. 19, Gunlagrahara Village,  
Lakshmipura Cross, Hesaraghatta Hobli,  
Bangalore North - 560097.

**EXECUTIVE DIRECTOR**  
BASIL WOODS NATURE SCHOOL  
DISE CODE : 29284100969  
Sy. No. 19, Gunlagrahara Village,  
Lakshmipura Cross, Hesaraghatta Hobli,  
Bangalore North - 560097.



17025. The Ultrasonic Pulse Velocity Test was conducted using the PUNDIT 6 (Portable Ultrasonic Non-Destructive Digital Indicating Tester), and according to the examination report conducted by the technical team of the sub-division in consultation with experts, the building has been found to be structurally sound.

As mentioned in the government letters referenced in (2) and (3), the evaluation fee, which is 0.05% of the building's value, amounts to Rs. 34,500/- (Rupees Thirty-Four Thousand Five Hundred Only), has been paid by BASIL WOODS NATURE SCHOOL through DD No. 002286, dated 29.11.2021, at EQUITAS Bank, Basaveshwaranagar Branch.

- It has been stated in the application from the National Institute of Value Education that the BASIL WOODS NATURE SCHOOL building has been constructed at Survey No. 19, Lakshmipur Cross, M.S. Palya Road, Bangalore. Accordingly, the building has been constructed at the specified location.

- The BASIL WOODS NATURE SCHOOL building has been constructed as per the approved plan from the Kasaghattapura Gram Panchayat, Hesargatta Hobli, Yelahanka Taluk, Bangalore.

**PRINCIPAL**  
**BASIL WOODS NATURE SCHOOL**  
 DISE CODE : 29284100969  
 Sy. No. 19, Guniagrahara Village,  
 Lakshmipura Cross, Hesarghatta Hobli,  
 Bangalore North - 560097.

**EXECUTIVE DIRECTOR**  
**BASIL WOODS NATURE SCHOOL**  
 DISE CODE : 29284100969  
 Sy. No. 19, Guniagrahara Village,  
 Lakshmipura Cross, Hesarghatta Hobli,  
 Bangalore North - 560097.



- The building has been constructed following the structural design provided by Dr. DJ. Suresh Kumar (Tejaswi Construction Company), Registration No: SJN-F139/2011-12.

- Ultrasonic Pulse Velocity Test

The Ultrasonic Pulse Velocity test for the compressive strength of in-situ concrete on columns, beams, and slabs at critical points was conducted using the "PUNDIT 6" (Portable Ultrasonic Non-Destructive Digital Indicating Tester) equipment from M/s. CNS Farnell, U.K., as per the guidelines in Indian Standards (IS: 516 (Part 5/Sec 1):2018). The test was carried out by M/s Karnataka Test House Pvt. Ltd, and the Assistant Executive Engineer, No. 2 North Sub-Division, Bangalore, has reported that the building has been found to be of excellent quality as per the results of the test.

- Recognizance, Visual Inspection of Building - Cracks, Distress, Dampness, etc. The inspection was conducted in collaboration with M/s Karnataka Test House Pvt. Ltd and the technical team of the Public Works Department. During the examination, it was found that the building is of excellent quality, as reported by the Assistant Executive Engineer, No. 2 North Sub-Division, Bangalore.

**PRINCIPAL**  
**BASIL WOODS NATURE SCHOOL**  
 DISTRICT CODE : 29284100969  
 Sy. No. 19, Guniagahara Village,  
 Lakshmipura Cross, Hesaraghatta Hobli,  
 Bangalore North - 560097.

**EXECUTIVE DIRECTOR**  
**BASIL WOODS NATURE SCHOOL**  
 DISTRICT CODE : 29284100969  
 Sy. No. 19, Guniagahara Village,  
 Lakshmipura Cross, Hesaraghatta Hobli,  
 Bangalore North - 560097.





- The building has been constructed in accordance with the National Building Code of India standards and has been certified as safe by Dr. DJ. Suresh Kumar (Tejaswi Construction Company), Registration No: SJN-F139/2011-12, as per the certificate provided by the institution.
- A Certificate for Structural Design Sufficiency, in accordance with the National Building Code of India 2016, has been issued by Dr. DJ. Suresh Kumar (Tejaswi Construction Company), Registration No: SJN-F139/2011-12. (Annex-C)
- A Certificate for the Engagement of the Builder/Constructor, in accordance with the National Building Code of India 2016, has been issued by Dr. DJ. Suresh Kumar (Tejaswi Construction Company), Registration No: SJN-F139/2011-12. (Annex-D)

Upon reviewing all the documents provided by the institution, including the certificate issued by M/s Karnataka Test House Pvt. Ltd & Dr. DJ. Suresh Kumar (Tejaswi Construction Company), Registration No: SJN-F139/2011-12, confirming the structural safety of the building, and considering the report provided by the technical team of the Public Works Department, along with a personal inspection, it has been concluded that the building is Structurally Stable. The undersigned, having personally examined

*[Signature]*  
**PRINCIPAL**  
 BASIL WOODS NATURE SCHOOL  
 DISE CODE : 29284100969  
 Sy. No. 19, Guniagrahara Village,  
 Lakshmipura Cross, Hesaraghatta Hobli,  
 Bangalore North - 560097.

*[Signature]*  
**EXECUTIVE DIRECTOR**  
 BASIL WOODS NATURE SCHOOL  
 DISE CODE : 29284100969  
 Sy. No. 19, Guniagrahara Village,  
 Lakshmipura Cross, Hesaraghatta Hobli,  
 Bangalore North - 560097.

the building on 04.12.2021, has issued a no-objection certificate confirming that the BASIL WOODS NATURE SCHOOL building is structurally stable, subject to the following conditions.

- Moisture was found on the walls of the basement toilets, the ground-floor computer lab and staff room, and the first-floor lecture halls. Immediate repairs should be made.
- Install flagging concrete around the building.
- Immediate repairs should be carried out for the damaged disposal pipes.
- Construct a parapet of required height around the terrace of the building.

Further, regarding the Non-Structural Elements (Infrastructural facilities) of the proposed building, a no-objection certificate must be obtained after inspection by a team comprising of the Civil Engineer, Health Officer, Revenue Officer, Psychologist, Fire Officer, and Local Authority Officials. Additionally, the "Fire Safety Certificate" must be obtained from the Chief Fire Officer.

Yours faithfully,  
Sd/-

Executive Engineer,  
PWD, Bangalore Division,  
Bangalore.

**EXECUTIVE DIRECTOR**  
**BASIL WOODS NATURE SCHOOL**  
**DISE CODE : 29284100969**  
Sy. No. 19, Guniagrahara Village,  
Lakshmipura Cross, Hesaraghatta Hobli,  
Bangalore North - 560097.

TRUE TRANSLATION FROM  
KANNADA

Version to ..ENGLISH  
Translated by: Mubarak Khan, B.A., LL.M, KSET, (Ph.D)  
SIU Translation Centre (Regd.)  
in labour Dept. Govt of Karnataka  
Regd.No. 17/119/CE/0055/2004  
BBMP Licence No: SQ20119645148990121  
SF 28-A, HMS Complex,  
Cubbonpet Main Road, Bengaluru-02

Organiser

**PRINCIPAL**  
**BASIL WOODS NATURE SCHOOL**  
**DISE CODE : 29284100969**  
Sy. No. 19, Guniagrahara Village,  
Lakshmipura Cross, Hesaraghatta Hobli,  
Bangalore North - 560097.